

Initial Calibrations - Claas 106, 108, MF 8460 Combines									
Monitor Serial No:									
Flow Sensor Serial No:									
Header Sensor:		Standard							
					Box Cal:		Voltage Cal:		
					Scale Factor:	1.0	Sensor Cal:		
T1:		10	T2:		5	T3:		8	
Sprocket Teeth:		7	Elevator Pulses/Rev:			4			
Note: Be sure to set the above values before harvesting!									
Claas 106, 108, MF 8460									
	Soybeans	All	All Other						
Crop	<u>/Edible Beans</u>	<u>Corn Types</u>	<u>Grains</u>						
C1	100	100	100						
C2	240	480	240						
C3	480	960	480						
C4	720	1440	720						
C5	960	1920	960						
C6	1200	2400	1200						
C7	1440	2880	1440						
C8	1680	3360	1680						
C9	1920	3840	1920						
C10	2160	4320	2160						
C11	2400	4800	2400						
S1	75	0	75						
M1	400	650	705						
% OFFSET	+4.7	+3.5	+2.0						
Ag Leader Technology									
Rev N/C						8-15-97			